

تبدیل زاویه (درجه) به شیب (درصد)

تبدیل شیب به زاویه		تبدیل زاویه به شیب	
زاویه (درجه)	شیب %	شیب %	زاویه (درجه)
0.57	1	0.9	0.5
1.15	2	1.7	1.0
1.72	3	2.6	1.5
2.29	4	3.5	2.0
2.86	5	4.4	2.5
3.43	6	5.2	3.0
4.00	7	6.1	3.5
4.57	8	7.0	4.0
5.14	9	7.8	4.5
5.71	10	8.7	5.0
6.28	11	9.6	5.5
6.84	12	10.4	6.0
7.41	13	11.3	6.5
7.97	14	12.2	7.0
8.53	15	13.0	7.5
9.09	16	13.9	8.0
9.65	17	14.7	8.5
10.20	18	15.6	9.0
10.76	19	16.4	9.5
11.31	20	17.3	10.0
11.86	21	18.1	10.5
12.41	22	19.0	11.0
12.95	23	19.8	11.5
13.50	24	20.6	12.0
14.04	25	21.5	12.5
14.57	26	22.3	13.0
15.11	27	23.1	13.5
15.64	28	24.0	14.0
16.17	29	24.8	14.5
16.70	30	25.6	15.0